



*Capt. Phineas T. McHenry, Ltd.*

*Marine Surveyor  
38 Oak Hill Lane  
Elkton, MD 21921  
410-287-2028*

*khenry1492@verizon.net  
www.kenhenrymarinesurvey.com*



**HULL CONSTRUCTION (cont.)**

- b) The catwalks are starting to come up. The paint is peeling away from the catwalks.



- c) I did note a considerable amount of rot around both pilot houses along the top and bottom edges. Evidence of water leakage can be seen along the bottom.



- d) Cabin floors in both cabins are missing.
- e) The interior cargo deck has seven 4' x 8' sheets of plywood running down the middle, and the plywood for the sides are missing.
- f) The interior bottom has been fibreglassed over and has marine growth on the interior, as well a fish swimming in the interior.
- g) The rub rails are in very poor condition.

**HULL CONSTRUCTION (cont.)**



h) The exterior bottom could not be inspected at the time of my inspection due to the water level.

**HULL CONSTRUCTION (cont.)**

- i) The hull appeared to be holding its shape, and there was no noticeable distortion to the hull at the time of my inspection.



- j) The cabin hatches are in poor condition.



**COMMENTS**

The vessel has been neglected for many years and is in poor condition. There are many structural issues.

My research shows that canal boats are very popular, and there is a market for these boats for tours, restaurants, second homes, rentals, etc. This boat is restorable and, in my professional opinion, has some value.

Since the vessel was inspected in the water, the condition of the bottom is unknown.

**CONCLUSION**

With consideration given to the condition of the vessel, it is hereby my professional opinion that an appraised value for said vessel can be placed at \$7,116.00.

**PRICE JUSTIFICATION**

I established the price of \$7,116.00 by taking the purchase price for said canal boat of \$147,317.00 and depreciating the price by 25% for the first year and 5% for each year after. Since the boat was built in 1982 and being appraised in 2016, I depreciated the boat for 34 years, arriving at a value of \$20,332.61. However, since the canal boat is deemed unsafe for use, but can still be restored, I reduced the value by 65%.

# *Capt. Phineas T. McHenry, Ltd.*

**MARINE SURVEYOR ♦ MARINE CONSULTANT  
38 OAK HILL LANE ♦ ELKTON, MD 21921  
410-287-2028**

**APPRAISAL REPORT #xxxx**

**PAGE 6 of 6**

## **DISCLAIMER**

My inspection of this vessel represents reasonable care and skill. My conclusion does not constitute a guarantee or warranty of the vessel's condition or of its parts, but it is an expression of my opinion only. No liability is assumed by me for errors of judgment or omission, or for subsequent structural or mechanical weakness in the vessel.

This report should be considered as an entire document. No single section is meant to be used, except as part of the whole. It is current to the named client for 30 days of undisturbed layup of the vessel's first use. Subsequent updating and transfer of the survey is solely the right of the surveyor.

The content of this report remains the sole property of said marine surveyor and may not be used without the author of the survey written permission. The use of this report shall constitute an acceptance of the above mentioned conditions.

**REPORT SIGNED AND SUBMITTED WITHOUT PREJUDICE**

Kenneth E. Henry, Sr., AMS® #370  
Marine Surveyor/President

**MEMBER ABYC, ASNT, and IAAI  
SOCIETY OF ACCREDITED MARINE SURVEYORS  
INTERNATIONAL INSTITUTE OF MARINE SURVEYING**